

Control panel of the shaper

Display of the cutter position

Data acquisition system

Proximity sensor used for the automatization of the data acquisition system

Slide used to adjust the depth of cut

Triaxial loadcell for the measurement of the force components

Manual gearbox to select the cutting speed

Vice for fixing the samples

Positioning system of the samples

UMONS
Université de Mons

**POLYTECH
MONS**

PMDS
Diamond Cutting Tools